

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2019

Submitted Date:

10/15/2019

Document Number:

696101414**FIELD INSPECTION FORM**Loc ID 305204 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
James, Brian		bjames@hpres.com	All Inspections
Brown, Tim		tbrown@hpres.com	MIT

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275567	WELL	TA	10/01/2018	GW	123-22642	ROTHE 23-31	TA

General Comment:

[This is a MECHANICAL INTEGRITY TEST | MIT inspection](#)
[Well: Temporarily Abandoned | TA.](#)
[Reference: Form 42 Doc #402186870.](#)

Inspected Facilities									
Facility ID:	275567	Type:	WELL	API Number:	123-22642	Status:	TA	Insp. Status:	TA
Workover									
Comment:	<p>Mechanical Integrity Test MIT to maintain Shut-In/Temporarily Abandoned SI/TA status.</p> <p>Tbg Depth: 6299' ; CIBP@6390'. ITP @ 43 psig, ICP @ 43 psig, Bradenhead @ 0 psig, pressure Csg to 407 psig and isolate wellbore from pump, 5 minute: Tbg @ 43 psig, Csg @ 404 psig, Bradenhead @ 0 psig 10 minute: Tbg @ 43 psig, Csg @ 402 psig, Bradenhead @ 0 psig 15 minute: Tbg @ 43 psig, Csg @ 402 psig, Bradenhead @ 0 psig Release pressure, SIW, RDMO. Loss / Gain: -5 psig.</p>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
COGCC Inspection Report Summary: On TUE 10/15/2019 at approximately 11:41 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: ROTHE-65N63W /31NESW Location ID: 305204 Well Name: Rothe 23-31 API: 05-123-22642 Location County: Weld County, Colorado Weather: Damp from prior rain / snow. While there, I observed: Well(s): 1 ; Temporarily Abandoned TA. Witnessed Mechanical Integrity Test MIT to maintain Shut-In/Temporarily Abandoned SI/TA status. Observed MIT recording on pump truck computer. During this inspection, NO possible compliance issues were observed. This is a summary of the inspection report.	evinsb	10/15/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101414	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963777
696101418	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963772
696101419	MIT - Pressure chart	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963773