

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2019

Submitted Date:

10/16/2019

Document Number:

693501649

FIELD INSPECTION FORM

Loc ID 321500 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10369
Name of Operator: NATURAL RESOURCE GROUP INC
Address: 801 WEST MINERAL AVE STE 202
City: LITTLETON State: CO Zip: 80120

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Bacon, Duane	303-545-2620/303-579-6353	energyoilandgas@gmail.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240972	WELL	SI	04/01/2018	OW	014-08760	SHANNON-ROBERTS 3	SI

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date:
Corrective Action:			

Good Housekeeping:			
Type	TRASH		
Comment:	Trash: furniture next to crude oil tank containment berm		
Corrective Action:	Comply with Rule 603 f	Date:	08/01/2018
Type	OTHER		
Comment:	Stained soil under crude oil load out line.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	05/29/2019
Type	WEEDS		
Comment:	Dead weeds around location		
Corrective Action:	Comply with rule 603 f	Date:	05/13/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:		Date:	

Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Mechanical issue: crude oil load out Valve or bull plug appears to be leaking. Crude oil tank appears to be eroding away around base of tank.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 07/19/2018

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240972 Type: WELL API Number: 014-08760 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday October 16, 2019 at approximately 11:13AM, I Randy Silver, Conducted a follow up on-site inspection at a Natural Resource Group site Shannon-Roberts #3. Doc#'s 693500461, 685100683, 691400734 and 688402028 at API# 05-014-08760 in Broomfield county Colorado. While there, I observed a production site. During this inspection, the following possible compliance issues were observed: Mechanical issue. Rule 605 d Corrective action date of 7-19-18 see photo 5 Trash: Rule 603 f Corrective action date of 8-1-18 See photo 4,6 Stained soil: Rule 907 e Corrective action date of 5-29-19 See photo 5 Weeds/trash: Rule 603 f Corrective action date of 5-13-19 See photo 4,6 This is a follow up inspection per doc# 685100683 . Mechanical issue appears not to have been corrected at time of inspection. Well has been SI since April of 2018 does not require MIT at this time. This a follow up inspection per doc# 691400134 and 688402028 Mechanical issue and Trash appears not to have been corrected at time of inspection. Gauge hatch has been closed at last inspection. Follow up insptection to Doc#693500461 Corrective actions were present: stained soil and Weeds/trash. Natural Resource Group Inc - Operator #10369 bankruptcy was converted to Chapter 7 on September 5/2019. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	10/16/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501650	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964790