

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2019

Submitted Date:

10/16/2019

Document Number:

699300383**FIELD INSPECTION FORM**

Loc ID 336425 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241654	WELL	PR	04/25/1978	OW	123-09443	STATE 11	IO

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	adequate			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Stained soil around WH			
Corrective Action:	For localized stained soils or oily waste -"Properly treat or dispose of oily waste in accordance with 907.e."			Date: 10/31/2019
Type	TRASH			
Comment:	Broken PU belts at base of PJ			
Corrective Action:	comply with Rule 603.f			Date: 10/23/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Chainlink topped with barbwire			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	Fabricated angle iron			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment			# 1	corrective date
Comment:			electric panel, transformers, and meter box	
Corrective Action:			Date:	
Type: Prime Mover			# 1	
Comment:			electric motor	

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241654 Type: WELL API Number: 123-09443 Status: PR Insp. Status: IO

Producing Well

Comment:

Corrective Action:

Date:

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: Well appears to be SI belts from electric motor to pump jack appear to be broken and lying ay PJ base

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Wednesday 10/16/19 at approximately 1430 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the State #11 KP Kauffman, at API #05-123-09433 in Weld County Colorado.
 While there, I observed a SI wellsite.
 During this inspection the following possible compliance issues were observed:
 603.f housekeeping: Broken PU belts at the base of the PJ. CA date 10/31/2019 see photo #4
 907.e Spotty stained soil: stained soil around
 WH. CA date 10/23/2019 see photo #3.
 Location is dry, weather is clear.
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
 Continuing education COGCC Inspection Report Summary.
 This is a summary of inspection report.

revasr

10/16/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300384	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965209