

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2019

Submitted Date:

10/17/2019

Document Number:

696101430

FIELD INSPECTION FORM

Loc ID 332237 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
James, Brian		bjames@hpres.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271412	WELL	PR	07/01/2019	GW	123-22021	SIEBRING 41-32	PR
430337	TANK BATTERY	AC			-	Siebring Pad 5-63-32-16H	AO

General Comment:

This is a WELL & BATTERY inspection.
Well(s): 1 ; Producing | PR.
Battery: Active
Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).
(Well(s): 5 ; 2: Producing | PR ; 1: Shut-In | SI ; 2:Temporarily Abandoned | TA).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Methanol		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Emergency number NOT posted at wellsite. Refer to Rule 210.b. (30 Days). * Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019. See photo #1.	
Corrective Action:	* Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019. See photo #1.	Date: 11/18/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Surrounded by earth berms		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel		

Corrective Action:		Date:
Equipment:		corrective date
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 2	
Comment: 2: Unused & unmarked vertical risers near gas meter runs. Valves are shut and plugged. Refer to Rule 603.f regarding marking / LOTO requirements for unused risers. See photos #3, 4.		
Corrective Action:		Date:
Type: Gas Meter Run	# 3	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Appears plumbed to surface		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: Containers: 1: Methanol w/ drip containment. Placarded.		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 0	
Comment: Removed		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment: Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: _____
 Corrective Action: _____ Date: _____

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		

Comment: _____
 Corrective Action: _____ Date: _____

Paint

Condition _____

Other (Content) _____
 Other (Capacity) _____
 Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ crude oil tanks.](#)
 Corrective Action: _____ Date: _____

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.363010,-104.450910

Comment: [Equalizer lines connect creude oil tanks.](#)
 Corrective Action: _____ Date: _____

Paint

Condition Adequate _____

Other (Content) _____
 Other (Capacity) _____
 Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: [Shares berms w/ produced H2O tank.](#)
 Corrective Action: _____ Date: _____

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type _____

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 271412 Type: WELL API Number: 123-22021 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing | PR.](#)

Corrective Action:

Date:

Facility ID: 430337 Type: TANK API Number: - Status: AC Insp. Status: AO

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 10/17/2019 at approximately 14:01 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: SIEBRING /41-32 Location ID: 332237 Well Name: Siebring 41-32 API: 05-123-22021 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s): 1 ; Producing PR. Battery: Active Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267). (Well(s): 5 ; 2: Producing PR ; 1: Shut-In SI ; 2:Temporarily Abandoned TA).</p> <p>During this inspection, the following possible compliance issues were observed. 1.) Emergency number NOT posted at wellsite. Refer to Rule 210.b. (30 Days). * Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019. See photo #1.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/17/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101431	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966453