

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2019

Submitted Date:

10/18/2019

Document Number:

687905665**FIELD INSPECTION FORM**Loc ID 325489 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214878	WELL	PR	03/01/2019	GW	067-06482	PINE RIVER 04-32 1	PR

**General Comment:**[Site inspection and equipment inventory with photos at the end of this report.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Access through forest service locked gate.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Labels and placards posted on signs and on tank.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	TANK BATTERY			
Comment:	T-post and hogwire around tank battery.			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Fenced in barbed wire.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Flow Line	# 6			corrective date
Comment:	1-3" flowline from wellhead to separator. 1-1" flowline from separator to pumpjack engine fuel gas. 1-1" flowline from separator to heated produced water tanks fuel gas. 1-2" flowline from separator dump valve to produced water tanks. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Wellhead with block valve assembly installed.			

Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	(1) on separator stack and (2) on heated produced water tanks.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas engine on pumping unit.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 214878	Type: WELL	API Number: 067-06482	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil tank.
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			
Gradient Terraces	Pass	Ditches	Pass			

Comment: [Stormwater BMP's appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905666	Overview photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967208">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967208</a>