

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2019

Submitted Date:

10/18/2019

Document Number:

696101440**FIELD INSPECTION FORM**Loc ID 310743 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296788	WELL	SI	05/01/2019	OW	123-26908	NORTH PLATTE 43-13	SI

**General Comment:**[This is an Alternate Method Inspection | AMI.](#)[Well\(s\): 1; Shut-In | SI.](#)[Battery: Active.](#)[Centralized Battery serves 2 Location IDs \(310744, 310743\).](#)[\(Well\(s\): 2; Producing | PR\) ; Well\(s\): 1; Shut-In | SI\).](#)[Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.](#)[Follow-up to Field Inspection Report Doc. #696101376 dated 10/07/2019.](#)[This inspection only comprises the mitigation of prior inspection Corrective Actions.](#)

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	WEEDS		
Comment:	<p>Prior insp: Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, &amp; control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 10/15/2019.</p> <p>This insp: * Weeds NOW appear mitigated at wellsite. See photos #1, 2. Photo #2 Operator provided photo for AML.</p>		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 296788 Type: WELL API Number: 123-26908 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Shut-In.  
Last production: 04/2019.

Corrective Action: Date:

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 10/18/2019 at approximately 13:30 hrs. I, Bret Evins, conducted an Alternate Method Inspection   AMI at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: North Platte /43-13 Pad  Location ID: 310743  Location County: Weld County, Colorado  Weather: Dry</p> <p>Observations from prior on-site inspection:  While there, I observed:  Well(s): 1; Shut-In   SI.  Battery: Active.  Centralized Battery serves 2 Location IDs (310744, 310743).  (Well(s): 2; Producing   PR) ; Well(s): 1; Shut-In   SI).</p> <p>Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report Doc. #696101376 dated 10/07/2019.  This inspection only comprises the mitigation of prior inspection Corrective Actions.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed:  1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance.  Remove, manage, &amp; control weeds around wellsite.  Comply with Rule 603.f.  Corrective Action date: 10/15/2019.  * Weeds NOW appear mitigated at wellsite.  See photos #1, 2.  Photo #2 Operator provided photo for AMI.</p> <p>NO: New / Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/18/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101441	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967215">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967215</a>

