

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/18/2019

Submitted Date:

10/18/2019

Document Number:

699500219**FIELD INSPECTION FORM**
 Loc ID 433796 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433795	WELL	PR	06/06/2014	OW	123-37784	Lochbuie 2E-31H D165	PR
433797	WELL	PR	06/01/2019	OW	123-37785	Lochbuie 2F-31H D165	PR
433798	WELL	PR	06/06/2014	OW	123-37786	Lochbuie 2D-31H D165	PR
433800	WELL	PR	06/01/2019	OW	123-37787	Lochbuie 2A-31H D165	PR
433801	WELL	PR	06/06/2014	OW	123-37788	Lochbuie 2G-31H D165	PR
433802	WELL	PR	06/06/2014	OW	123-37789	Lochbuie 2B-31H D165	PR
433803	WELL	SI	05/01/2019	OW	123-37790	Lochbuie 2C-31H D165	SI
434443	WELL	PR	06/06/2014	OW	123-38169	Lochbuie 2H-31H D165	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: 6' Chain link fence

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

9

Comment: automation

Corrective Action:

Date:

Type: Other

#

Comment: SLB Hydraulic rod lift

Corrective Action:

Date:

Type: Bradenhead

8

Comment:

Corrective Action:

Date:

Type: Prime Mover

2

Comment: Hydraulic pump

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: <u>433795</u>	Type: <u>WELL</u>	API Number: <u>123-37784</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433797</u>	Type: <u>WELL</u>	API Number: <u>123-37785</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433798</u>	Type: <u>WELL</u>	API Number: <u>123-37786</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433800</u>	Type: <u>WELL</u>	API Number: <u>123-37787</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433801</u>	Type: <u>WELL</u>	API Number: <u>123-37788</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433802</u>	Type: <u>WELL</u>	API Number: <u>123-37789</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>433803</u>	Type: <u>WELL</u>	API Number: <u>123-37790</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>434443</u>	Type: <u>WELL</u>	API Number: <u>123-38169</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing WellComment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	10/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500220	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967295