

Inspection Photos
Operator: Seeley Oil
Co.Location/API #: 083-06539
Date: 10-11-2019



Photo 1. View of the project area from the southwestern edge facing center. The majority of the southern and western project area are not in use and need to be reclaimed.



Photo 2. View of riser within the northwestern project area, needing removal.



Photo 3. View of another riser within the western project area, needing removal.



Photo 4. View of more risers, needing removal.



Photo 5. View of the western project area graveled and not in use, needing reclamation.



Photo 6. View of reference area vegetation comprised of pinyon juniper woodland.