

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2019

Submitted Date:

10/21/2019

Document Number:

688800637**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Donahue, Jessica	(303) 888-4862	jessica.donahue@oxbow.com	
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
464354	SPILL OR RELEASE	AC	05/17/2019		-	Hotchkiss Federal 20-12D	EI

General Comment:

On October 16, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Gunnison Energy LLC Spill/Release Point ID #464354. For the most recent field inspection report of this facility, please refer to document #693900451.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	DEBRIS		
Comment:	Cut off sections of pipe left on site.		
Corrective Action:	Comply with Rule 603.f		Date: 11/21/2019
Type	TRASH		
Comment:	Stock piled soil contains what appears to be trash sandbag material.		
Corrective Action:	Comply with Rule 603.f.		Date: 10/31/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gathering Line	# 2		corrective date
Comment:	Steel gas and water gathering lines were exposed in open excavation during this field inspection.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB):	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	In Process					

Comment: [Excavated material stockpiled along pipeline trench does not have any storm water BMPs.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 11/21/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On October 16, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Gunnison Energy LLC Spill/Release Point ID #464354. For the most recent field inspection report of this facility, please refer to document #693900451. During this inspection an open trench was observed with a replaced section of the water gathering line exposed. The cut out sections of pipe and pipeline debris (wood, sandbag fabric, etc.) were present. Several dead Juniper trees were observed on the downhill side of the ROW, down gradient of the release point.</p>	hughesjo	10/21/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800638	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4968669