

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2019

Submitted Date:

10/21/2019

Document Number:

694900618

FIELD INSPECTION FORM

Loc ID 413453 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: GRIZZLY OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 27 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, vanguard		aaxelson@vnrenergy.com	
, vanguard		sghan@vnrenergy.com	SR. EH&S
, vanguard		scollett@vnrenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412476	WELL	PR	10/27/2009	GW	045-18461	KAUFMAN 34D-24-692	PR
412477	WELL	PR	11/18/2009	GW	045-18460	KAUFMAN 34B-24-692	PR
412478	WELL	PR	10/19/2009	GW	045-18454	KAUFMAN 33A-24-692	PR
412479	WELL	PR	10/18/2009	GW	045-18455	KAUFMAN 34C-24-692	PR
412480	WELL	PR	11/18/2009	GW	045-18456	KAUFMAN 33D-24-692	PR
412481	WELL	PR	11/11/2009	GW	045-18457	KAUFMAN 33C-24-692	PR
412482	WELL	PR	10/19/2009	GW	045-18458	KAUFMAN 33B-24-692	PR
412483	WELL	PR	11/11/2009	GW	045-18459	KAUFMAN 34A-24-692	PR
417876	WELL	PR	12/13/2011	GW	045-19645	KAUFMAN 24A-24-692	PR
417878	WELL	PR	12/13/2011	GW	045-19646	KAUFMAN 23B-24-692	PR
417879	WELL	PR	11/17/2011	GW	045-19647	KAUFMAN 24D-24-692	PR
417880	WELL	PR	12/13/2011	GW	045-19648	KAUFMAN 23D-24-692	PR
417887	WELL	PR	11/17/2011	GW	045-19649	KAUFMAN 23C-24-692	PR
417895	WELL	PR	12/13/2011	GW	045-19650	KAUFMAN 24C-24-692	PR
417896	WELL	PR	11/17/2011	GW	045-19651	KAUFMAN 23A-24-692	PR
417899	WELL	PR	12/01/2011	GW	045-19652	KAUFMAN 24B-24-692	PR

General Comment:

COGCC Inspection Report Summary

On Monday 10/21/19 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Grizzly Kaufman 7 Pad, at location # 413453 in Garfield County, Colorado.

While there, I observed Normal production operations. All C/A(s) have been completed from FIRR document # 402187886.

During this inspection the following possible compliance issues were observed:

Signage does not reflect current operator name.

Install correct signage within 90 days.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	All Signage does not reflect current operator name.		
Corrective Action:	Install correct signage within 90 days.		Date: 01/21/2020
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	all C/A(s) have been completed		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 16		corrective date
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 16		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	chemical tanks		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:	500 gallon tank for braden heads				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLS	HEATED STEEL AST		,
Comment:	2 tanks not heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:	braden heads are open		
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	412476	Type:	WELL	API Number:	045-18461	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	412477	Type:	WELL	API Number:	045-18460	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	412478	Type:	WELL	API Number:	045-18454	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	412479	Type:	WELL	API Number:	045-18455	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	412480	Type:	WELL	API Number:	045-18456	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	412481	Type:	WELL	API Number:	045-18457	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	412482	Type:	WELL	API Number:	045-18458	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	412483	Type:	WELL	API Number:	045-18459	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				

Facility ID: 417876	Type: WELL	API Number: 045-19645	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 417878	Type: WELL	API Number: 045-19646	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 417879	Type: WELL	API Number: 045-19647	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 417880	Type: WELL	API Number: 045-19648	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 417887	Type: WELL	API Number: 045-19649	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 417895	Type: WELL	API Number: 045-19650	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 417896	Type: WELL	API Number: 045-19651	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 417899	Type: WELL	API Number: 045-19652	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Gravel				
Gravel						
Berms		Compaction				
Compaction		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900622	694900618	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4968812