

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2019

Submitted Date:

10/15/2019

Document Number:

694500142

FIELD INSPECTION FORM

Loc ID 316766 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10490
Name of Operator: ENERGY QUEST II LLC
Address: 4526 RESEARCH FOREST DR #200
City: THE WOODLANDS State: TX Zip: 77381

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Booco, Randy		boocosinc@aol.com	
jeff teare		jeff.teare@energyquest.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
113016	PIT	AC			-	PEOC - NVG 41-23H	EI
232758	WELL	PR	02/09/1991	OW	107-06173	PEOC-NVG 41-23H	EI

General Comment:

On 8/5/2019 COGCC staff, Kris Neidel inspected the PEOC-NVG 41-23H. and pit facility id 113016. Weather was mostly clear and 75 degrees. This inspection address specific Environmental items documented here and does not necessary address previous required action required. The pit has been closed sometime in the past. The well was SI at the time of inspection. It appeared that the emission control device on location was SI at the time of inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			
Crude Oil	WELLHEAD	<= 1 bbl			
Comment: wellhead is oily					
Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date:	10/30/2019
Crude Oil	Flow Line	<= 1 bbl			
Comment: oily soil near wellhead on flowlines					
Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date:	10/30/2019

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 113016 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 232758 Type: WELL API Number: 107-06173 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402210686	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963703
694500145	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963684