

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2019

Submitted Date:

10/22/2019

Document Number:

688800641

FIELD INSPECTION FORM

Loc ID 423375 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		inspection@sginterests.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418790	PIT	AC			-	MCINTYRE FLOWBACK 4	EI
418791	PIT	AC			-	MCINTYRE FLOWBACK 3	EI
421066	CENTRALIZED EP WASTE MGMT FAC	AC	01/04/2011		-	McIntyre Flowback Pits #3 and #4 421066	EI

General Comment:

[On October 16, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests McIntyre Flowback Pits #3 and #4. For the most recent field inspection report of this facility, please refer to document #693900469.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Location sign mounted to perimeter fence near access gate.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Production equipment from SG Federal 11-90-26 #1 stored in the SW corner of the facility, per Form 4 document #401538826. All equipment has been labeled "temporarily decommissioned"		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Perimeter fencing around location.		
Corrective Action:		Date:	
Type	PIT		
Comment:	Pit Facility ID #418790 and #418791 are both fenced/netted.		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 418790 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 418791 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 421066 Type: CENTRALIZE API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Compaction	Pass			
Berms	Pass					
Sediment Traps	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Multiwell Reuse/ Recycling Lined: YES Pit ID: 418791 Lat: 39.076340 Long: -107.413600

Reference Point: OTHER Other: Center Length: _____ Width: _____

Lining:

Liner Type: HDPE Liner Condition: Adequate

Comment: Lower Pit (#3)

Corrective Action:

Date: _____

Fencing:

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: Fence/Net Combo Netting Condition: Holes

Comment: Several holes observed in netting during this inspection. Previously repaired areas require attention.

Corrective Action: Net or fence pit to prevent access per rule 902.d.

Date: 10/23/2019

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action:

Date: _____

Type: Multiwell Reuse/ Recycling Lined: YES Pit ID: 418790 Lat: 39.077050 Long: -107.413200

Reference Point: OTHER Other: Center Length: _____ Width: _____

Lining:

Liner Type: HDPE Liner Condition: Adequate

Comment:

Corrective Action:

Date: _____

Fencing:

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment:

Corrective Action:

Date: _____

