

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2019

Submitted Date:

10/09/2019

Document Number:

693200424**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Murray, Richard _____ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		lprescott@laramie-energy.com	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
468517	SPILL OR RELEASE	AC	10/02/2019		-	Kobe-Chevron Valve Can	AC

General Comment:[COGCC joint inspection with EPS J. Heil and Western Integrity Inspector R. Murray](#)[Engineering Integrity Inspection performed on October 9, 2019. In response to initial form 19, document number 402195259.](#)

Inspected FacilitiesFacility ID: 468517 Type: SPILL OR API Number: - Status: AC Insp. Status: AC**Flowline**

#1	Type: Non-Well Site	1 of Lines	
----	---------------------	------------	--

Flowline DescriptionFlowline Type: Non-Well SiteSize: 10"Material: Carbon SteelVariance: NoAge: 5-10 YrsContents: Produced WaterIntegrity SummaryFailures: OtherSpills: YesRepairs Made: Yes

Coatings:

H2S: NoCathodic Protection: NoPressure TestingWitnessed: No

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: COGCC is requesting records that pertain to flowline that released fluidCorrective Action: Provide annual pressure test results for effected flowline, Maintenance records and operation performed at site. Provide Root cause of release. Via FIRR and email to Western Integrity inspectorDate: 10/23/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402211066	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963986
693200426	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963909