

**Response to September 24, 2019 Inspection
Document Number: 679601640**

COGCC conducted an inspection of the Steve J Steve J 18 Pad (Location ID 333001) on September 24, 2019 (Document 679601640).

During that inspection, COGCC made the following observations:

COGCC Stormwater comment: *Erosion to location. INSTALL OR REPAIR REQUIRED BMPs PER RULE 1002.F. (Corrective Action Date: October 24, 2019) See attached photo #11-13.*

Stormwater Corrective Action: Install, repair, or replace required BMPs per Rule 1002.f. in accordance with good engineering practices.

Response: Noble addressed the erosion issues noted by COGCC. Erosion was backfilled, slopes repaired and stabilized, and control measures added as described in the photo log below. Noble looks to continually improve their stormwater program, and we welcome further discussion regarding these repairs.

COGCC – 9/24/19



COGCC Photo 11. Erosion

Noble Energy – 10/12/19



Photo NBL1. Erosion back-filled, and slopes compacted and tracked.

Name: Steve J 18 Pad

Location ID: 333001

COGCC – 9/24/19



COGCC Photo 12. Erosion,

Noble Energy – 10/12/19



Photo NBL2. Erosion back-filled, and slopes compacted and tracked.

Name: Steve J 18 Pad

Location ID: 333001

COGCC – 9/24/19



COGCC Photo 13. Erosion

Noble Energy – 10/12/19



Photo NBL3. Filtrexx installed outside fence. Erosion repaired, and sloped compacted and tracked.