

Inspection Photos
Location Name: KERI 33-18
API#: 05-071-06469
INSP. #: 695101571



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: KERI 33-18
API#: 05-071-06469
INSP. #: 695101571



PHOTO 3: AREA OF IMPACTED SOIL AROUND AND UNDER ENGINE SKID. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-18-19



PHOTO 4: CONTAINMENT BURMS AROUND PRODUCED WATER TANK IS IN ADEQUATE FOR PROPER CONTAINMENT. Repair or install berms or other secondary containment devices per Rule 906.d.(1). CA DATE 11-18-19