

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2019

Submitted Date:

10/23/2019

Document Number:

687905680

### FIELD INSPECTION FORM

Loc ID 325930 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone        | Email                       | Comment                               |
|------------------|--------------|-----------------------------|---------------------------------------|
| Inspections, All |              | SanJuanCOGCC@bp.com         | <a href="#">All Inspections</a>       |
| Labowskie, Steve |              | steve.labowskie@state.co.us | <a href="#">COGCC</a>                 |
| Beebe, Sabre     | 970-779-9398 | Sabre.Beebe@bpx.com         | <a href="#">SW Inspection Reports</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 215584      | WELL | PR     | 11/27/1988  | GW         | 067-07189 | HOLMAN CANYON 1 | PR          |

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

| Location   |                    |  |  |                 |
|--|--------------------|--|--|-----------------|
| <b>Lease Road:</b>                                     |                    |  |  |                 |
|  | Type               | Access   |  |                 |
|  | comment:           | Gravel access road.  |  |                 |
|  | Corrective Action: |  |  | Date:           |
| Overall Good: <input type="checkbox"/>                 |                    |  |  |                 |
| <b>Signs/Marker:</b>                                   |                    |  |  |                 |
|  | Type               | WELLHEAD   |  |                 |
|  | Comment:           | Sign posted at entrance to location.   |  |                 |
|  | Corrective Action: |  |  | Date:           |
| Emergency Contact Number:                              |                    |  |  |                 |
|  | Comment:           | Contact information posted on sign.  |  |                 |
|  | Corrective Action: |  |  | Date: _____     |
| Overall Good: <input type="checkbox"/>                 |                    |  |  |                 |
| <b>Spills:</b>   |                    |  |  |                 |
| Type   | Area               | Volume   |  |                 |
| In Containment: No                                     |                    |  |  |                 |
|  | Comment:           |  |  |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |                    |  |  |                 |
| <b>Fencing/:</b>                                       |                    |  |  |                 |
|  | Type               | SEPARATOR  |  |                 |
|  | Comment:           | Cattle panels around separator and meter house.  |  |                 |
|  | Corrective Action: |  |  | Date:           |
|  | Type               | WELLHEAD   |  |                 |
|  | Comment:           | Cattle panels around wellhead.   |  |                 |
|  | Corrective Action: |  |  | Date:           |
| <b>Equipment:</b>                                      |                    |  |  |                 |
| Type: Bradenhead                                       | # 1                |  |  | corrective date |
|  | Comment:           | PVC bradenhead access.   |  |                 |
|  | Corrective Action: |  |  | Date:           |
| Type: Bird Protectors                                  | # 1                |  |  |                 |
|  | Comment:           | On separator stack.  |  |                 |
|  | Corrective Action: |  |  | Date:           |
| Type: Vertical Heated Separator                        | # 1                |  |  |                 |
|  | Comment:           |  |  |                 |
|  | Corrective Action: |  |  | Date:           |
| Type: Flow Line  | # 4                |  |  |                 |
|  | Comment:           | 1-3" flowline from wellhead to separator. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to offsite dogleg. |  |                 |

|                           |   |       |  |
|---------------------------|---|-------|--|
| Corrective Action:        |   | Date: |  |
| Type: Gas Meter Run       | # 1   |       |  |
| Comment:                  |   |       |  |
| Corrective Action:        |   | Date: |  |
| Type: Ancillary equipment | # 1   |       |  |
| Comment:                  | Wellhead with block valve assembly installed. |       |  |
| Corrective Action:        |   | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 215584 Type: WELL API Number: 067-07189 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gradient Terraces | Pass            | Ditches                 | Pass                  |               |                          |         |
| Ditches           | Pass            | Culverts                | Pass                  |               |                          |         |
| Compaction        | Pass            | Compaction              | Pass                  |               |                          |         |
| Gravel            | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description     | URL   |
|--------------|-----------------|---|
| 687905681    | Overview photo. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970555">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970555</a> |