

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2019

Submitted Date:

10/23/2019

Document Number:

694900642

## FIELD INSPECTION FORM

Loc ID 335236 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE****Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Contact Information:**

| Contact Name | Phone        | Email                              | Comment |
|--------------|--------------|------------------------------------|---------|
| , TEP        | 970-285-9377 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 211197      | WELL | PR     | 03/27/1995  | GW         | 045-06956 | CLOUGH RMV 25-20  | PR          |
| 260583      | WELL | PR     | 06/09/2001  | GW         | 045-07874 | CLOUGH RWF 433-20 | PR          |

**General Comment:**[COGCC Inspection Report Summary](#)

On Wednesday 10/23/19 at approximately 12:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 25-20, at Location # 335236 in Garfield County, Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective Action  |        |  | Date: |

Overall Good:

|                           |     |  |             |
|---------------------------|-----|--|-------------|
| Emergency Contact Number: |     |  |             |
| Comment:                  | 911 |  |             |
| Corrective Action:        |     |  | Date: _____ |

|                           |        |  |       |
|---------------------------|--------|--|-------|
| <b>Good Housekeeping:</b> |        |  |       |
| Type                      | DEBRIS |  |       |
| Comment:                  |        |  |       |
| Corrective Action:        |        |  | Date: |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

|                    |              |  |       |
|--------------------|--------------|--|-------|
| <b>Fencing/:</b>   |              |  |       |
| Type               | TANK BATTERY |  |       |
| Comment:           | hog panel    |  |       |
| Corrective Action: |              |  | Date: |
| Type               | SEPARATOR    |  |       |
| Comment:           | hog panel    |  |       |
| Corrective Action: |              |  | Date: |
| Type               | WELLHEAD     |  |       |
| Comment:           | steel fence  |  |       |
| Corrective Action: |              |  | Date: |

|                                   |     |  |                 |
|-----------------------------------|-----|--|-----------------|
| <b>Equipment:</b>                 |     |  | corrective date |
| Type: Horizontal Heated Separator | # 4 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Bird Protectors             | # 4 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |
| Type: Plunger Lift                | # 2 |  |                 |
| Comment:                          |     |  |                 |
| Corrective Action:                |     |  | Date:           |

**Tanks and Berms:**

| Contents       | # | Capacity  | Type      | Tank ID | SE GPS |
|----------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST |         | ,      |

Comment: centralized containment  
80 bbl tank

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Paint

Condition Adequate \_\_\_\_\_

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

| Contents   | # | Capacity | Type      | Tank ID | SE GPS |
|------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 200 BBLS | STEEL AST |         | ,      |

Comment: centralized containment

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Paint

Condition Adequate \_\_\_\_\_

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent     | Base Sufficient     | Adequate    |

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flaring:**

Type \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 211197 Type: WELL API Number: 045-06956 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 260583 Type: WELL API Number: 045-07874 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 |                         |                       |               |                          |         |
| Berms            |                 | Compaction              |                       |               |                          |         |
| Compaction       |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 694900650    | 694900642   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970568</a> |