

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2019

Submitted Date:

10/23/2019

Document Number:

699300420**FIELD INSPECTION FORM**

Loc ID 318387 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241202	WELL	PR	11/03/1976	OW	123-08990	UPRR 42 PAN AM AF 2	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Faded well name not legible		
Corrective Action:	Comply with Rule 210.e	Date:	10/18/2019

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Spoty stained soil around WH and under flowline		
Corrective Action:	Comply with Rule 907.e Properly treat or dispose of localized stained soils or oily waste.		Date: 10/18/2019
Type	WEEDS		
Comment:	Weeds growing around Electric panel, transformers and meter box.		
Corrective Action:	Comply with Rule 603.f		Date: 09/28/2019
Type	OTHER		
Comment:	Mechanical issue PU appears to have a leaking gasket		
Corrective Action:	Comply with Rule 605.d Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition		Date: 10/18/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Electric panel, transformers and meter box. Fabricated steel pipe		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog fence		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	fabricated angle iron Hog fence		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, transformers and meter box		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241202 Type: WELL API Number: 123-08990 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 10/23/2019 at approximately 1100hrs. Inspector Robbie Revas, Conducted an on-site inspection at the UPRR 42 Pan Am AF #2 KP Kauffman, at API #05-123-08990 in Weld County Colorado.</p> <p>While there, I observed a producing wellsite. This is a follow up inspection per Doc.#699300202</p> <p>During this inspection the following possible compliance issues appear to have not been addressed and are now delinquent:</p> <p>Housekeeping: Weeds growing around electric transformers. Comply with rule 603.f 10 days for weeds. CA date 9/28/2019 see photo #4.</p> <p>Housekeeping: Spotty stained soil around WH and under flow line. Comply with Rule 907.e 30 days to remove stained soil. CA date 10/18/2019. See photos #2 and 3.</p> <p>Mechanical condition: PU appears to have a leaking gasket. Comply with Rule 605.d Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. CA date 10/18/2019 See photo # 5.</p> <p>Signs: WH sign is faded wellsite name is not legible. Comply with Rule 210.e Install/Replace sign. CA date 10/18/2019 See photo #1.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	10/23/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300421	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970958">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970958</a>