



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Fabricated steel tubing		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electric panel, transformers and meter box. Fabricated steel tubing		
Corrective Action:		Date:	

**Equipment:**

Type	Quantity	Comment	Corrective Action	Date	corrective date
Bradenhead	# 1	appears to be plumbed to surface			
Pump Jack	# 1				
Prime Mover	# 1	Electric motor			
Ancillary equipment	# 1	Electric panel, transformers and meter box			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241085 Type: WELL API Number: 123-08873 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 10/23/19 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection Suckla Brown unit #12 KP Kauffman, API # 123-08873 in Weld County Colorado.                      While there, I observed a producing well site. This is a follow up inspection per Doc. # 699300015                      During this inspection the following possible compliance issues appear to have been addressed:                      Stained soil: Rule 907.e stained soil appears to have been removed. See attached photo #3                      Sign faded: Rule 210.e WH sign has been replaced See attached photo #2                      Mechanical issue: Rule 605.d 1" valve on tubing appears to have been tightened/replaced. See attached photo #3                      Trash on location: unused electric box has been removed. See attached photo #6                      Weeds growing on access road: Weeds have been cut. See attached photo # 1                      Weather conditions Cloudy and windy Location is dry                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.                      This is a continuing education inspection.</p>	revasr	10/23/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300431	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970963">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970963</a>