

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2019

Submitted Date:

10/22/2019

Document Number:

689703659**FIELD INSPECTION FORM**Loc ID 324419 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 28600Name of Operator: EXXON MOBIL CORPORATIONAddress: P O BOX 4358City: HOUSTON State: TX Zip: 77210-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	970-675-4122	Jessica_Dooling@xtoenergy.com	Piceance EHS Supervisor
Pesicka, Conor		conor.pesicka@state.co.us	
Reid, Van	970-675-4106	Van_reid@xtoenergy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Burger, Craig		craig.burger@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290949	WELL	PA	12/16/2010	GW	045-14231	COLONY FEE 595-7A1	WK

**General Comment:**Follow Up Field inspectionOn 10/17/2019 at approximately 1130 hrs, I, Inspector Mike Longworth, conducted a follow up field inspection at EXXON MOBIL CORPORATION COLONY FEE 595-7A1 Location # 324419 in Garfield County, Colorado  
All corrective actions have been addressed from 09/10/2019 Inspection # 689703516

**Location****Lease Road:**

Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Contact number added to battery sign. 970-675-4117		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency contact number added to battery sign. 911	
Corrective Action:		Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290949	Type:	WELL	API Number:	045-14231	Status:	PA	Insp. Status:	WK
Workover									
Comment: <input type="text" value="SPN Rig 14 Milling production casing at 500'"/>									
Corrective Action: <input type="text"/> Date: <input type="text"/>									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass					
Compaction	Pass					
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703660	Inspection 689703659 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971179">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971179</a>