

Inspection Photos
Operator Name: Caerus
Location ID: 323864



Flowlines removed



**3 flowlines Tagged documented in inspection
693200408**

Inspection Photos
Operator Name: Caerus
Location ID: 323864



Inspection photo from inspection document
689703474



3 flowlines 1" removed

Inspection Photos
Operator Name: Caerus
Location ID: 323864



Inspection photo from inspection document
689703474



flowline marked and documented on inspection
693200408