

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2019

Submitted Date:

10/24/2019

Document Number:

690101477

**FIELD INSPECTION FORM**

Loc ID 321509 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone | Email                                 | Comment |
|--------------------|-------|---------------------------------------|---------|
| Ford, Blake        |       | bford@extractionog.com                |         |
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us         |         |
|                    |       | COGCCInspections@extracti<br>onog.com |         |

**Inspected Facilities:**

| Facility ID | Type                         | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------------------------------|--------|-------------|------------|-----------|----------------------|-------------|
| 203470      | WELL                         | PR     | 02/24/1998  | GW         | 014-09029 | FEDOROWICZ 1-17      | EG          |
| 459677      | OFF-<br>LOCATION<br>FLOWLINE | AC     | 12/10/2018  |            | -         | Wellhead Line 17NESW | EG          |
| 461223      | OFF-<br>LOCATION<br>FLOWLINE | AC     | 01/28/2019  |            | -         | Wellhead Line 17NESW | EG          |

**General Comment:**

Engineering Integrity inspection performed on October 16th, 2019 in response to initial form 19 spill report Doc #402209305 received by COGCC on 10/15/2019 that outlines: While removing a partially-buried produced-water vessel at the FEDOROWICZ-61S68W 17NESW (Location ID: 321509), legacy suspected soil impacts were observed.

Details of observations made during this field inspection are located in the flowline and comment sections of this report. Photos uploaded.

**Inspected Facilities**

Facility ID: 203470 Type: WELL API Number: 014-09029 Status: PR Insp. Status: EG

**Flowline**

| #1 | Type: | of Lines |
|----|-------|----------|
|----|-------|----------|

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Fedorowicz 1-17) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402180328 received on 09/18/2019. Extraction contract personnel (Moon) on location at the time of this field inspection were completing excavation and remediation work. All flowlines (wellhead/ dump/ process) have been removed. No flowline risers were observed during this field inspection at the wellhead or facility/ battery.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 459677 Type: OFF- API Number: - Status: AC Insp. Status: EG

Facility ID: 461223 Type: OFF- API Number: - Status: AC Insp. Status: EG

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| *Note: There is (1) disconnected/ out of service gas gathering meter run on the east side of the location:  | maclarej | 10/24/2019 |
| The following COGCC final reclamation rule(s) are applicable: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well. |          |            |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description  | URL   |
|--------------|--|---|
| 690101478    | Wellhead flowline removed                          | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971334">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971334</a> |
| 690101479    | Well site PA (View to west); No flowline risers    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971335">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971335</a> |
| 690101480    | Excavation work at battery; inactive gas meter run | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971336">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971336</a> |