

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2019

Submitted Date:

10/24/2019

Document Number:

693200427

FIELD INSPECTION FORM

Loc ID 323864 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		COGCC.inspections@caerus oilandgas.com	All Piceance inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	
Longworth, Mike		michael.longworth@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211035	WELL	PR	03/01/2019	GW	045-06793	GASAWAY (FEDERAL) 6206 (27-1)	PR

General Comment:

Engineering Integrity Inspection performed as follow up inspection, to field inspection document number 693200408
Corrective actions noted in inspection 693200408 for lock out tag flowlines risers and remove risers has been satisfied.

Inspected Facilities

Facility ID: 211035 Type: WELL API Number: 045-06793 Status: PR Insp. Status: PR

Flowline

#1	Type: Process Piping	3 of Lines
----	----------------------	------------

Flowline Description

Flowline Type: Process Piping Size: Other Material: Carbon Steel
 Variance: No Age: 5-10 Yrs Contents: Other

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Flowlines from wellhead to edge of location have been removed
see photo log

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200429	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971337