

CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360



CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360



Dead weed debris around tanks and heat unit.



CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360



Dead weed debris



**CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360**



Dead weed debris



Dead weed debris

**CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360**



Dead weed debris



Dead weed debris



**CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360**



Operator name and numbers blacked out.



Damaged fiberglass secondary containment

**CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360**



Damaged fiberglass secondary containment



Damaged fiberglass secondary containment

**CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360**



Washed out around drainage pipe.



Washed out around drainage pipe.

**CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360**



Washed out around drainage pipe.

CAERUS PICEANCE LLC
FEDERAL-68S97W 14SENE (OH14)
Location # 334360



Unmaintained waddles along ditch.