

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2019

Submitted Date:

10/24/2019

Document Number:

693801199

FIELD INSPECTION FORM

Loc ID 311866 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10453
Name of Operator: PARADOX UPSTREAM LLC
Address: PO BOX 220
City: NATURITA State: CO Zip: 81422

Findings:

- 18 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	
Hankins, Neil	970-428-2742	davidh@paradoxresources.com	
Miller, Mandy	970-739-3786	mandym@paradoxresources.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232862	WELL	PR	09/01/2018	GW	113-06051	COCKLEBUR DRAW UNIT 1	PR

General Comment:

COGCC staff performed a followup field inspection on 10/23/2019. Followup to inspection doc#680402081 on 10/23/2019. Issues were found requiring corrective action. CAs from previous inspection not completed. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
Lease Road:			
Type	Main		
comment:	BLM		
Corrective ActionL			Date:
Type	Access		
comment:	Road repaired. CA completed.		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead sign has wrong API#. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.b. CA from previous inspection not completed. CA date remains the same as previous inspection.		Date: <u>01/30/2018</u>
Type	BATTERY		
Comment:	Battery sign for Cocklebur Draw Metering Facility		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Maintain labels on battery and chemical tanks.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: <u>11/30/2019</u>
Emergency Contact Number:			
Comment:	435-587-2237 or 911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Reboiler water line broken and disconnected from tank. See attached photos.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA from previous inspection not completed. CA date remains the same as previous inspection.		Date: <u>12/06/2017</u>
Type	STORAGE OF SUPL		
Comment:	Chemical tank has blown over off stand and out of secondary containment.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>11/30/2019</u>
Type	WEEDS		
Comment:	Weeds maintained. CA completed.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence around wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe barricade around dehydrator		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Pipe barricade around separators		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	with glycol reboiler		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	<100 BBLs	PBV STEEL		37.968643,-108.521893	
Comment:	Glycol reboiler water tank. Unused equipment with disconnected line.					
Corrective Action:	Comply with Rule 603.f CA from previous inspection not completed. CA date remains the same as previous inspection.				Date:	12/08/2017

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			
Comment:				
Corrective Action: Maintain berms or remove tank. CA from previous inspection not completed. CA date remains the same as previous inspection.				Date: <u>12/08/2017</u>

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		37.968255,-108.521414
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:	
Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:	
Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 232862 Type: WELL API Number: 113-06051 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass	Material Handling And Spill Prevention	Fail	See houskeeping

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693801203	Inspection photos 10/23/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972425