

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2019

Submitted Date:

10/24/2019

Document Number:

688306097

**FIELD INSPECTION FORM**

Loc ID: 466338 Inspector Name: Sherman, Susan On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 81490  
Name of Operator: ST CROIX OPERATING INC  
Address: P O BOX 13799  
City: DENVER State: CO Zip: 80201

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Melnychenko, David	(303) 489-8428	davidpmel@yahoo.com	
Gottlob, Paul	(720) 420-5747	paul.gottlob@iptenergyservice.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466586	WELL	XX	08/09/2019		121-11087	SHOTGUN 1	DG

**General Comment:**

Production Cementing Followup Inspection

**Inspected Facilities**

Facility ID: 466586 Type: WELL API Number: 121-11087 Status: XX Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: WW Rig 12 Pusher/Rig Manager: Tom Thomas  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** Inspector did followup inspection to actual production cement pumping that occurred at ~2am. Pusher said that 240 sxs were pumped, not to surface. Land application in the dryland crop to the east of the location and off location landfill truck loading were taking place.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_