

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/18/2019

Submitted Date:

10/18/2019

Document Number:

699300400

FIELD INSPECTION FORM

Loc ID 318667 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241862	WELL	SI	04/01/2019	GW	123-09653	WILLIAM D. LANSDOWN UNIT C 1	SI

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Weeds overgrown on access road mostly dead			
Corrective Action	Comply with Rule 204			Date: 11/18/2019
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				Date:
Corrective Action:				Date:
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds overgrown around WH now dead			
Corrective Action:	Comply with Rule 603.f			Date: 10/25/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	hog fence			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Electric panel, transformers and meter box			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric motor			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				

Inspected Facilities

Facility ID: 241862 Type: WELL API Number: 123-09653 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 10/18/19 at approximately 0930 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at William D. Lansdown unit C #1 KP Kauffman at API #05-123-09653 in Weld County Colorado.</p> <p>While there, I observed a SI wellsite.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Rule 204: Weeds overgrown on access road, Repair and maintain lease road. CA date 11/18/2019 see photos #1.</p> <p>Rule 603.f: Housekeeping weeds growing around WH . CA date 10/25/2019 see photos #2 and 4.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	10/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402214926	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967490
699300401	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967487