

Eric Clubine 2
API: 05-103-05066
Inspection: 679705820



Photo 1. Location.

Eric Clubine 2
API: 05-103-05066
Inspection: 679705820



Photo 2. Well head.



Photo 3. Well head gage.

Eric Clubine 2
API: 05-103-05066
Inspection: 679705820



Photo 4. Separator & flowline.



Eric Clubine 2
API: 05-103-05066
Inspection: 679705820

Gas leaking



Photo 5. Flowline junction.



Photo 6. Gage at separator.

Eric Clubine 2
API: 05-103-05066
Inspection: 679705820



Photo 7. Gage at separator.



Photo 8. Gage at separator.

Eric Clubine 2
API: 05-103-05066
Inspection: 679705820



Photo 9. Container at separator.



Photo 10. Well head sign.