

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2019

Submitted Date:

10/21/2019

Document Number:

688306045**FIELD INSPECTION FORM**Loc ID 317243 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:24 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237370	WELL	PR	08/15/2006	OW	121-09871	CRONK 1	PR

General Comment:[High Priority Inspection/Reinspection](#)

Inspector contacted COGCC EPS about berms for tanks at the wellhead/south pit that a CA was previously written for on inspection 68830217 and they are not needed if the water/oil goes into the pit however, if work is done for those tanks by the operator, it is best practice to add berms at that location and a Form 27 is not needed to install that tank. A Form 27 is needed to remove the 300 bbl steel tank at the tank battery. The 8/10/2018 CA on installing berms is no longer applicable.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-867-1268

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	cattle wire panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	340 bbls, bermed		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	chemical container		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	300 BBLs	STEEL AST		,	
Comment:	Empty tank. Operator said that it is there because they want to install it at the wellhead/pit area.					
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		,	
Comment:	top is netted, tank is near pit west of wellhead					
Corrective Action:						Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	750 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	No Berms. Tank is upgradient of pit so produced water would flow into pit. Contacted COGCC EPS to determine if berms are needed and they are not.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	PBV STEEL		,
Comment:	Tank top is corroding, not in use (see attached photos). Inspector asked operator on 10/18/2019 to put bird covers over top of buried tank.				
Corrective Action:	Install or repair wildlife protection equipment				Date: 11/05/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:	animal holes in berm but tank is not in use (see attached photo)				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		,
Comment:	top is netted, tank is near pit west of wellhead				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	No Berms. Tank is upgradient of pit so produced water would flow into pit. Contacted COGCC EPS to determine if berms are needed and they are not.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV STEEL		,
Comment:	has bird protectors (see attached photo)				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate					
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Location Construction

Location ID: 237370 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	237370	Type:	WELL	API Number:	121-09871	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Feb 2019 last production reported to COGCC database. Update Form 7's to COGCC Production.								
Corrective Action:	Submit required Form 7(s) to COGCC per rule 309.							Date:	11/22/2019

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: _____

Corrective Action: _____

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:Fencing Type: None

Fencing Condition: _____

Comment: CRP

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: _____

Comment: pit west of skim tanks

Corrective Action: _____

Date: _____

Type: Produced WaterLined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:Fencing Type: None

Fencing Condition: _____

Comment: CRP

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment:					Date:
Corrective Action					
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>			
Comment:	<u>Near wellhead</u>				Date:
Corrective Action					
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:	
Reference Point:	Other:	Length:	Width:		
<u>Lining:</u>					
Liner Type:	Liner Condition:				
Comment:					Date:
Corrective Action					
<u>Fencing:</u>					
Fencing Type: <u>None</u>	Fencing Condition:				
Comment:	<u>CRP</u>				Date:
Corrective Action					
<u>Netting:</u>					
Netting Type:	Netting Condition:				
Comment:					Date:
Corrective Action					
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>			
Comment:	<u>Dry, pit near treater, furthest north pit</u>				Date:
Corrective Action					
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:	
Reference Point:	Other:	Length:	Width:		
<u>Lining:</u>					
Liner Type:	Liner Condition:				
Comment:					Date:
Corrective Action					
<u>Fencing:</u>					
Fencing Type: <u>None</u>	Fencing Condition:				
Comment:	<u>CRP</u>				Date:
Corrective Action					
<u>Netting:</u>					
Netting Type:	Netting Condition:				
Comment:					Date:
Corrective Action					
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>			
Comment:	<u>near buried skim tanks, south of dry pit</u>				Date:
Corrective Action					

Corrective Action		Date:
-------------------	--	-------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402215347	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967865
688306069	Fritzler Resources Cronk 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967863