



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electrical transformers, breaker panel and meter.Fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type	Quantity	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 1	Electrical transformers, breaker panel and meter.			
Pump Jack	# 1				
Prime Mover	# 1	Electric motor			
Bradenhead	# 1	Appears to be plumbed to surface			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240540 Type: WELL API Number: 123-08328 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Monday 10/28/2019 at approximately 0930 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at Robert Y. Sakata #1 KP Kauffman, at API # 05-123-08328 Weld County Colorado. This is a follow up inspection per Doc. # 699300129 and # 699300371.                      While there, I observed a SI well. Electric panel appears to be shut off. During this inspection the following compliance issue appears to have been addressed:                      Signs: At time of inspection wellhead sign appears to have been replaced with a new sign. See attached photo #1 and 2.                      Location is dry, weather is clear.                      No follow up inspection on this site inspection needs to be conducted. Corrective Action is addressed to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	10/28/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300458	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4974975">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4974975</a>