

**Inspection Photos**  
**Location Name: Zorro #32-4**  
**Location ID: 309483**



**Photo 1 loc pic**

**Photo 2 loc pic Weeds on location and around pit**

**Inspection Photos**  
**Location Name: Zorro #32-4**  
**Location ID: 309483**



**Photo 3 BMP's not in place to control erosion on access road to location. Ditch is approx. 3ft wide in places.**

**Photo 4 Sediment from Pic 3 erosion BMP issues not controlled and being carried off rightaway.**

**Inspection Photos**  
**Location Name: Zorro #32-4**  
**Location ID: 309483**



**Photo 5 Stained soil from HYD motor exhaust pipe.**



**Photo 6 Mechanical issues and stained soil around well head**