

Inspection Photos
Location Name: Abeyta #17-1
API: 05-067-05064



Damp area on location from separator to low spot on location.



Low lying area on location with wet soil.

Inspection Photos
Location Name: Abeyta #17-1
API: 05-067-05064



Standing water along flow path of release.



Stained soil and gravel within sound walls for pump jack.

Inspection Photos
Location Name: Abeyta #17-1
API: 05-067-05064



Standing water on location.



Low lying area near well head where release terminated.