

**Inspection Photos**  
**Location Name: Allison Unit #116S**  
**API: 05-067-09289**



**Stained gravel at exhaust outlet for prime mover.**



**Open topped below grade tank is not labeled.**

**Inspection Photos**  
**Location Name: Allison Unit #116S**  
**API: 05-067-09289**



**Soil within cellar for below grade tank is wet and stained.**



**Fluids and stained soil present within cellar for below grade tank.**



**Inspection Photos**  
**Location Name: Allison Unit #116S**  
**API: 05-067-09289**



**Skeletal remains within cellar for below grade tank.**



**Stained gravel beneath valve on lube oil container.**