

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2019

Submitted Date:

10/29/2019

Document Number:

679601821

FIELD INSPECTION FORMLoc ID 432487 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432487	LOCATION	AC			-	Tateyama 15U-434 Pad	AC
432488	WELL	PR	12/02/2013	OW	123-37130	Tateyama 15U-434	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Equipment not anchored. According to COGCC maps, location is in flood plains. See attached photo.		
Corrective Action:	Comply with Rule 603.H.(1).C.	Date:	10/26/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 432487 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 432488 Type: WELL API Number: 123-37130 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679601660. ONE(1) OUT OF TWO(2) CORRECTIVE ACTIONS IN PREVIOUS INSPECTION DOC#: 679601660 HAVE BEEN RESOLVED. THE INCOMPLETE CORRECTIVE ACTION HAS BEEN REASSIGNED TO THIS LOCATION. PLEASE REVIEW THE INSPECTION REPORT SUMMARY AND ATTACHED PHOTOS FOR DETAILS.</p> <p>**Weather conditions: Snow.</p> <p>COGCC Inspection Report Summary</p> <p>On Tuesday, October 29, 2019 at approximately 10:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at TATEYAMA 15U-434 PAD (PDC Energy), at location #: 432487 in WELD COUNTY Colorado.</p> <p>While there, I observed producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Appears horizontal separator is not anchored. According to COGCC Maps, location is in flood plains. COMPLY WITH RULE 603.H.(1).C. (Corrective Action Date: October 26, 2019) See attached photo #4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	10/29/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601822	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4976832