

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Direction sign to Location 324766.




Direction sign to Location 324766.



Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Location Sign.



Wellhead Sign.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Unmarked drum.



Unmarked chemical storage unit.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Unmarked and not cap riser.



Needle valve not capped.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Tank battery.



Tank battery.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



View of tank battery.



Separator enclosure.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Produced water tank.



Capped risers.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Trash can with oily rag and trash.



Trash can with oily rag and trash.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Drain valve at in-tank heater.



ECU and flare.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Capped riser.



Stainless steel line is considered trash and debris.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Trash and debris (rag).



Unlabeled AST

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Unlabeled AST



Oily staining in separator enclosure.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Blue hammer union weeping fluids.



Metal container in NW corner of Location with trash and debris.

Inspection Photos
Location Name: Fuqua 18-15
Location 324766



Metal container in NW corner of Location with trash and debris.



Trash (rag).