

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2019

Submitted Date:

10/30/2019

Document Number:

690900090

**FIELD INSPECTION FORM**Loc ID 324766 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10468

Name of Operator: THUNDER RIVER PRODUCTION LLC

Address: 4545 POST OAK PLACE DR #240

City: HOUSTON State: TX Zip: 77027

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
		dacockrell@thunder-river.com	
Waldron, Emily		emily.waldron@state.co.us	
		john.stevens@thunder-river.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299110	WELL	SI	10/01/2016	OW	057-06483	Fuqua 19-02-10-1H	EI

**General Comment:**

On October 18, 2019, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of Thunder River Production LLC's (Thunder River) Fuqua 18-15 Location (Location ID: 324766) API 057-10468 and REM 13906. Weather was partially sunny and temperatures about 33 degrees Fahrenheit. CAs from Inspection Doc # 689803087 have not been addressed. REM 6938 remains open for Spill ID 2222753 from a January 27, 2012 incident. Analytical results from a 2013 sampling event shows exceedance to Table 910-1 constituents.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Metal container in NW corner of Location with trash and debris. Stainless steel line near ECU and flare. Rags and trash on location.		
Corrective Action:	Comply with Rule 603.f .		Date: 11/06/2019
Type	UNUSED EQUIPMENT		
Comment:	Unmarked and uncapped flow lines.		
Corrective Action:	Comply with Rule 603.f . " For unused , unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.		Date: 11/01/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Separator	<= 1 bbl		
Comment:	Oil staining on ground surface near the separator.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.			Date: 11/30/2019

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--



**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: REM 6938 remains open for Spill ID 2222753 from a January 27, 2012 incident. Analytical results from a 2013 sampling event shows exceedance to Table 910-1 constituents.

Corrective Action: Provide a Supplemental Form 27 update regarding the spill and remediation. Contact area Environmental Protection Specialist (EPS) Kris Neidel at Kris.Neidel@state.co.us or 970-871-1963 within 2-weeks of this submittal (November 13, 2019) regarding this spill and remediation.

Date: 11/30/2019

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drums, Buckets, Containers	Other	Inadequate		
Comment	Unlabeled 55-gallon container, AST, and chemical container.			
Corrective Action	Install sign/labels to comply with Rule 210.d.			Date: 11/30/2019

**Spill/Remediation:**

Comment: REM 6938 remains open for Spill ID 2222753 from a January 27, 2012 incident. Analytical results from a 2013 sampling event shows exceedance to Table 910-1 constituents

Corrective Action: Provide a Supplemental Form 27 update regarding the spill and remediation. Contact area Environmental Protection Specialist (EPS) Kris Neidel at Kris.Neidel@state.co.us or 970-871-1963 within 2-weeks of this submittal (November 13, 2019) regarding this spill and remediation.

Date: 11/30/2019

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Signage directing oil field traffic to the Location is under previous operators' name.	fischera	10/30/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690900091	INSP Photo Fuqua 18-15 Location 324766 20191018	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4976910">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4976910</a>