

Inspection Photos

API: 05-071-06339

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 10/30/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06339 | Date: 10/30/2019

Inspection Photos



Photo 1. There is water leaking from the well head. There is ice buildup around the wellhead and water dripping. Corrective action was not properly performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06339 | Date: 10/30/2019