

Inspection Photos

API: 05-071-06300

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 10/30/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06300 | Date: 10/30/2019

Inspection Photos



Photo 1. There is water leaking from the well head. There is ice buildup around the wellhead and water dripping.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06300 | Date: 10/30/2019

Inspection Photos



Photo 2. Facing toward the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06300 | Date: 10/30/2019

Inspection Photos



Photo 3. Well sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06300 | Date: 10/30/2019