

# ARGENTA CDP

Corrective Actions Taken on the ARGENTA CDP for the COGCC INC.

# ARGENTA CDP 10/19/19



New signs have been installed with emergency contact information to comply with rule 210.d.

The cube shaped tank and open top below grade tank have been labeled to comply with rule 210.d.



The 80 bbl. fiberglass open top tank has been labeled to comply with Rule 210.d.



The produced water tank "Slop Tank # 1", has been labeled to comply with Rule 210.d. The stained soil from below the truck load line has been removed and properly disposed of to comply with Rule 906.a.



The stained soil around the southern compressor and southern facility fencing has been removed and properly disposed of to comply with Rule 906.a.



The stained soil at the northern edge of the compressor building and near the northern entrance of lower facility has been removed and properly disposed of to comply with Rule 906.a.



The unused equipment that was being stored on both levels of the facility has been removed comply with Rule 603.f.



Storm Water management controls have been maintained and established to stabilize storm water run on and run off. Cleaned the diversion around the upper level facility and established a drainage diversion along southern edge of the upper level facility to stabilize erosion and site degradation to comply with Rule 1002.f.



Storm Water management controls have been established to stabilize storm water run off. Installed rock run downs at the ends of the newly installed southern edge diversion to comply with Rule 1002.f.



Repaired erosion riling along southern edge of upper level to comply with Rule 1002.f.



The unused, unlabeled chemical container near the separator has been removed from location to comply with Rule 603.f.

