

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2019

Submitted Date:

10/31/2019

Document Number:

696101490

**FIELD INSPECTION FORM**

Loc ID 413974 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 8960  
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
 Address: 410 17TH STREET SUITE #1400  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432063	WELL	PR	09/01/2013	OW	123-36937	North Platte U-Y-34HNB	SI

**General Comment:**

This is a WELL inspection.  
 Well(s): 1 ; Shut-In | SI.  
 Battery: Shut-down | Inactive  
 Centralized Battery serves 2 Location IDs (429920, 413974).  
 (Well(s): 2 ; Shut-In | SI).  
 (2: Other wells associated w/ Location ID #413974 are connected to another Battery/Facility.)

Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type			
Comment:	Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign with company & well name NOT posted at wellsite. Refer to Rule 210.b. (60 Days). * Post sign with company & well name at wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/30/2019. See photo #1.		
Corrective Action:	* Post sign with company & well name at wellsite. Comply w/ Rule 210.b. See photo #1.		Date: 12/30/2019
<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No <input type="checkbox"/>			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type:	#		corrective date
Comment:	Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type: Bradenhead	# 1		

Comment: <a href="#">Appears plumbed to surface.</a>		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.363310,-104.414227
Comment: <a href="#">Centralized Battery serves 2 Location IDs (429920, 413974). Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.</a>					Date:
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

**Venting:**

Yes/No	NO	Date:
Comment:		Date:
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 432063 Type: WELL API Number: 123-36937 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI. Observed production valves closed.  
COGCC records indicate last production: 08/2019.

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 10/30/2019 at approximately 16:13 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC                      Location Name: North Platte /41-34 Pad                      Location ID: 413974                      Well Name: North Platte U-Y-34HNB                      API: 05-123-36937                      Location County: Weld County, Colorado                      Weather: Clear w/ prior snow cover</p> <p>While there, I observed:                      Well(s): 1 ; Shut-In   SI.                      Battery: Shut-down   Inactive</p> <p>Centralized Battery serves 2 Location IDs (429920, 413974).                      (Well(s): 2 ; Shut-In   SI).                      (2: Other wells associated w/ Location ID #413974 are connected to another Battery/Facility.)</p> <p>Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.</p> <p>During this inspection, the following possible compliance issues were observed:                      1.) Sign with company &amp; well name NOT posted at wellsite.                      Refer to Rule 210.b. (60 Days).                      * Post sign with company &amp; well name at wellsite.                      Comply w/ Rule 210.b.                      Corrective Action date: 12/30/2019.                      See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/31/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101491	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977807">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977807</a>