

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2019

Submitted Date:

11/01/2019

Document Number:

694900726

FIELD INSPECTION FORM

 Loc ID 335108 Inspector Name: Ramsey, Scott On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282178	WELL	PR	12/22/2005	GW	045-11694	CLOUGH RWF 311-22	PR
282179	WELL	PR	09/14/2006	GW	045-11693	CLOUGH RWF 421-22	PR
282180	WELL	PR	02/13/2007	GW	045-11692	CLOUGH RWF 321-22	PR
282181	WELL	PR	09/15/2006	GW	045-11691	CLOUGH RWF 411-22	PR
282253	WELL	PR	12/28/2005	GW	045-11709	CLOUGH RWF 521-22	PR
282254	WELL	PR	12/28/2005	GW	045-11708	CLOUGH RWF 511-22	PR
282265	WELL	PR	09/15/2006	GW	045-11698	CLOUGH RWF 412-22	PR
282267	WELL	PR	10/10/2006	GW	045-11697	CLOUGH RWF 312-22	PR

General Comment:

COGCC Inspection Report Summary

On Friday 11/1/19 at approximately 1:00 PM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP 162-22 Pad, at Location # 335108 in Garfield County, Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:	
Comment:	911
Corrective Action:	
	Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____


Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	hog panel		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	hog panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	282178	Type:	WELL	API Number:	045-11694	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	282179	Type:	WELL	API Number:	045-11693	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	282180	Type:	WELL	API Number:	045-11692	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	282181	Type:	WELL	API Number:	045-11691	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	282253	Type:	WELL	API Number:	045-11709	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	282254	Type:	WELL	API Number:	045-11708	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	282265	Type:	WELL	API Number:	045-11698	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	282267	Type:	WELL	API Number:	045-11697	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
Ditches		Compaction				
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900733	694900726	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978805