

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2019

Submitted Date:

11/02/2019

Document Number:

696101496

FIELD INSPECTION FORMLoc ID 331805 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266119	WELL	TA	12/31/2018	GW	123-21329	DOW 41-33	PA

General Comment:

This is an Alternate Method Inspection | AMI.
Well(s): 1 ; Plugged & Abandoned | PA.
Battery: Shut-down | Inactive.

Centralized Battery formerly served 1 Location ID (331805). (This Location).
Centralized Battery serves 1 Location IDs (423850).
(Well(s): 1 ; Temporarily Abandoned | TA).
Battery SE corner GPS: 40.361146, -104.434408

Refer to Field Inspection Doc. #696101448 and/or Location ID #423850 for Battery / Facility, Equipment info formerly associated with this P&A'd well.

Follow-up to Field Inspection Report Doc. #696101450 dated 10/21/2019.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 266119 Type: WELL API Number: 123-21329 Status: TA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment:

Well appears to be Plugged & Abandoned | PA.

Casing appears to be cut & capped.

Form 6 Doc # 402082586 indicates cut / cap date: 06/07/2019. Approval Pending.

Prior insp:

Abandoned flow line riser at wellsite has NOT been marked or Locked-out / Tagged-out | LOTO.

Refer to Rule 603.f.

Mark & Lock-out / Tag-out unused flowline riser at wellsite.

Comply w/ Rule 603.f.

Corrective Action date: Open

This insp:

* Unused flowline riser at wellsite & separator NOW appears to be marked & Locked-out / Tagged-out | LOTO.

See photos #1-3.

Photos #2, 3 provided by Operator.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 11/01/2019 at approximately 15:00 hrs. I, Bret Evins, conducted an Alternate Method Inspection AMI at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte 44-11-28HZ /Facility Location ID: 331805 Well Name: DOW 41-33 API: 05-123-21329 Location County: Weld County, Colorado Weather: Clear, w/ partial prior snow cover.</p> <p>Observations from prior on-site inspection: Well(s): 1 ; Plugged & Abandoned PA. Battery: Shut-down Inactive. Centralized Battery formerly served 1 Location ID (331805). (This Location). Centralized Battery serves 1 other Location ID (423850). (Well(s): 1 ; Temporarily Abandoned TA). Battery SE corner GPS: 40.361146, -104.434408</p> <p>Refer to Field Inspection Doc. #696101448 and/or Location ID #423850 for Battery / Facility, Equipment info formerly associated with this P&A'd well.</p> <p>Follow-up to Field Inspection Report Doc. #696101450 dated 10/21/2019.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Abandoned flow line riser at wellsite has NOT been marked or Locked-out Tagged-out. Refer to Rule 603.f. Mark & Lock-out / Tag-out unused flowline riser at wellsite. Comply w/ Rule 603.f. Corrective Action date: Open * Unused flowline riser at wellsite & separator NOW appears to be marked & Locked-out Tagged-out. See photos #1-3. Photos #2, 3 provided by Operator.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/02/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101497	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4979061