

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021




Photo 1: Wellhead



Photo 2: Tank Battery Sign

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 3: Tank Battery



Photo 4: NFPA placarding added to North tanks

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Colorado Oil and Gas Conservation Commission
40.52489, -104.67071, 1444.2m, 9°
Oct 31, 2019 13:03:01

Photo 5: Labeling added to south tank



Colorado Oil and Gas Conservation Commission
40.52492, -104.67081, 1442.8m, 66°
Oct 31, 2019 13:03:17

Photo 6: Labeling added to south tank

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 7: Close up of labeling on south tanks



Photo 8: Hole repaired in berm wall

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 9: Hole repaired in berm wall



Photo 10: No Labeling/Placard on H2O tank

Inspection Photos
Location Name: Lamb 33-24
Location ID: 310021



Photo 11: BBLs on wrong side of tank.