

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2019

Submitted Date:

11/04/2019

Document Number:

696101498

FIELD INSPECTION FORM

Loc ID 327001 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SRC ENERGY INC
Address: 1675 BROADWAY SUITE 2600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@srcenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246193	WELL	SI	07/01/2019	GW	123-13990	MOSSBERG-PM J30-9	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL & ABANDONED BATTERY** inspection.
Well(s): 1 ; Plugged & Abandoned | PA.
Battery: Abandoned | All equipment appears removed.
Reclamation progressing.

Abandoned Centralized Battery formerly served 2 Location IDs (327001, 326979).
(Well(s): 2 ; Plugged & Abandoned | PA).
Abandoned Battery SE corner GPS coordinates: 40.367923, -104.818148

Location

Lease Road:			
	Type	Access	
	comment:	Adequate. Farm road.	
Corrective Action:			Date:

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 0		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 0		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 0		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 246193 Type: WELL API Number: 123-13990 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to be Plugged & Abandoned | PA. All equipment appears removed.
Casing appears to be cut & capped.
Form 6 doc # 402219888 indicates cut / cap date: 09/17/2019. Approval Pending.
Reclamation progressing.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 11/04/2019 at approximately 11:18 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: SRC ENERGY INC Location Name: MOSSBERG-PM-65N66W /30NESE Location ID: 327001 Well Name: Mossberg-PM J30-9 API: 05-123-13990 Location County: Weld County, Colorado Weather: Cloudy w/ muddy areas</p> <p>While there, I observed: Well(s): 1 ; Plugged & Abandoned PA. Battery: Abandoned All equipment appears removed. Reclamation progressing.</p> <p>Abandoned Centralized Battery formerly served 2 Location IDs (327001, 326979). (Well(s): 2 ; Plugged & Abandoned PA). Abandoned Battery SE corner GPS coordinates: 40.367923, -104.818148</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/04/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101499	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4979967