

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2019

Submitted Date:

11/04/2019

Document Number:

696101500

FIELD INSPECTION FORM

Loc ID 326979 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SRC ENERGY INC
Address: 1675 BROADWAY SUITE 2600
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@srcenergy.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246168	WELL	PA	03/08/2019	OW	123-13965	MOSSBERG PMJ 30-10	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL & ABANDONED BATTERY** inspection.
Well(s): 1 ; Plugged & Abandoned | PA.
Battery: Abandoned | All equipment appears removed.
Reclamation progressing.

Abandoned Centralized Battery formerly served 2 Location IDs (327001, 326979).
(Well(s): 2 ; Plugged & Abandoned | PA).
Abandoned Battery SE corner GPS coordinates: 40.367923,-104.818148

Refer to Field Inspection Report Doc. #696101498 and/or Location ID #327001 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report Doc. #696100722 dated 03/30/2019.

Location

Lease Road:			
Type	Access		
comment:	Adequate. Farm road.		
Corrective Action			Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused Equipment at Abandoned wellsite. Well fencing, wellhead parts, cutoff casing needs removed. Refer to Rule 603.f. (30 Days). Corrective Action Date: 05/06/2019.</p> <p>This insp: *Unused Equipment at Abandoned wellsite. Well fencing, wellhead parts, cutoff casing NOW appears removed. See photos #1, 2.</p>		
Corrective Action:			Date:

Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused & Unmarked gas meter run riser at Battery site needs removed. Refer to Rule 603.f. Corrective Action Date: 05/06/2019.</p> <p>This insp: * Unused & Unmarked gas meter run riser at Abandoned Battery site NOW appears removed. See photos #3, 4.</p>		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 246168 Type: WELL API Number: 123-13965 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well Appears to have been Plugged & Abandoned (PA). PA well appears cut & capped. Form 6 #401986834 indicates plugging date: 03/08/2019 (Approved). Reclamation progressing.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				

Comment: [Farm road.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 11/04/2019 at approximately 11:26 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: MOSSBERG PMJ-65N66W /30NWSE Location ID: 326979 Well Name: Mossberg PMJ 30-10 API: 05-123-13965 Location County: Weld County, Colorado Weather: Cloudy w/ muddy areas</p> <p>While there, I observed: Well(s): 1 ; Plugged & Abandoned PA. Battery: Abandoned All equipment appears removed. Reclamation progressing.</p> <p>Abandoned Centralized Battery formerly served 2 Location IDs (327001, 326979). (Well(s): 2 ; Plugged & Abandoned PA). Abandoned Battery SE corner GPS coordinates: 40.367923,-104.818148</p> <p>Refer to Field Inspection Report Doc. #696101498 and/or Location ID #327001 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report Doc. #696100722 dated 03/30/2019.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed:</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed:</p> <p>1.) Unused Equipment at Abandoned wellsite. Well fencing, wellhead parts, cutoff casing needs removed. Refer to Rule 603.f. (30 Days). Corrective Action Date: 05/06/2019. *Unused Equipment at Abandoned wellsite. Well fencing, wellhead parts, cutoff casing NOW appears removed. See photos #1, 2.</p> <p>2.) Unused & Unmarked gas meter run riser at Battery site needs removed. Refer to Rule 603.f. Corrective Action Date: 05/06/2019. * Unused & Unmarked gas meter run riser at Abandoned Battery site NOW appears removed. See photos #3, 4.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>11/04/2019</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101503	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980053