

## Inspection Photos

Location Name: N Parachute EF12A-19 L19595 Pad & L19-595 Dumpline release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: October 31, 2019



Photo #1 – Pad sign.



Photo #2 – Overview of north end of pad.



## Inspection Photos

Location Name: N Parachute EF12A-19 L19595 Pad & L19-595 Dumpline release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: October 31, 2019



**Photo #3 – Backfilled excavation area, located east of separators.**



**Photo #4 – View of covered pothole east of former excavation area.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: N Parachute EF12A-19 L19595 Pad & L19-595 Dumpline release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: October 31, 2019



Photo #5 – Additional covered potholes located northeast of former excavation area.



Photo #6 – Flowline riser north of separators has been tagged out.



## Inspection Photos

Location Name: N Parachute EF12A-19 L19595 Pad & L19-595 Dumpline release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: October 31, 2019



**Photo #7 – Flowline risers east of separators. Flowline riser with 1" valve has been tagged out.**



**Photo #8 – Uncovered pothole located west of separators.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: N Parachute EF12A-19 L19595 Pad & L19-595 Dumpline release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: October 31, 2019



**Photo #9 – Downhill area east of backfilled excavation. No hydrocarbon stains or odors were observed in this area on inspection date.**



**Photo #10 – Sediment trap located north of backfilled excavation. No hydrocarbon stains or odors were observed in this area on inspection date.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources