

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2019

Submitted Date:

11/04/2019

Document Number:

687905752

FIELD INSPECTION FORM

Loc ID 441327 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 22 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441326	WELL	PR	09/22/2015	LO	067-09927	Tubbs 32-6-9 B 4	PR
441328	WELL	PR	09/21/2015	LO	067-09928	Tubbs 32-6-9 A 2	PR

General Comment:

[Site inspection and equipment inventory with photos at the end of this report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Maintained gravel access road to location.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on secondary containment ring and tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs posted at entrance to location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Contact information posted on signs		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	Broken off pieces of exhaust tubing laying on the ground at west end of #B4 pumpjack.		
Corrective Action:	Remove trash per Rule 603.f.	Date:	11/11/2019
Type	UNUSED EQUIPMENT		
Comment:	#B4 Pumpjack has been disconnected from wellhead. horsehead and long arms have been removed from gearbox and set along side of location. Sucker rod has been pulled and is sitting along side gearbox. Unused muffler laying on ground along side gearbox and unused disconnected engine oil tank sitting along side gearbox.		
Corrective Action:	Remove unused equipment or return to service per Rule 603.f.	Date:	12/04/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location.		
Corrective Action:		Date:	
Equipment:			
Type: Pump Jack	# 2		corrective date
Comment:	#A2 pumping unit currently in service. #B4 pumping unit dismantled and not in use. See housekeeping section for unused equipment CA.		
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 2	
Comment:	Duell unit.	
Corrective Action:		Date:
Type: Prime Mover	# 2	
Comment:	#A2 natural gas powered engine exhaust has oil stained soil/gravel around edge of pumpjack skid and around muffler on ground.	
Corrective Action:	Clean-up stained soil/gravel per Rule 1002.f.(2)	Date: 11/11/2019
Type: Bradenhead	# 2	
Comment:	PVC bradenhead access on both wellheads.	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:	Inside duell separator building.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Sound panels around #A2 pumping unit.	
Corrective Action:		Date:
Type: Flow Line	# 13	
Comment:	4-4" flowlines from wellheads to duell separator. 2-2" flowlines from separator blowdown to produced water tank. 2-1" flowlines from separator to pumpjack engines fuel gas. 2-2" flowlines from separator dump valves to produced water tank. 2-4" flowlines from separator merging to 1-4" flowline to offsite dogleg.	
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Wellheads with block valve assemblies installed.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 441326 Type: WELL API Number: 067-09927 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 441328 Type: WELL API Number: 067-09928 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass	Gravel	Pass			
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention on engine oil tanks.
Rip Rap	Pass					
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905753	Overview photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980147
687905754	Disconnected (unused) pumpjack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980148
687905755	Unused equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980150
687905756	Unused equipment muffler, rod, oil tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980151
687905757	Unused equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980153
687905758	Stained gravel/soil from muffler.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980154
687905759	Stained gravel/soil from muffler.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980155
687905760	Trash west end of pumpjack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980157