

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/04/2019

Submitted Date:

11/04/2019

Document Number:

699500240

FIELD INSPECTION FORM
 Loc ID 318894 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242405	WELL	PR	03/20/1995	OW	123-10196	YOXALL FARMS 10	PR
432048	WELL	PA	07/10/2013	DA	123-36927	HOWARD 2N-33HZ	PA
432049	WELL	PR	04/11/2014	OW	123-36928	HOWARD 27N-28HZ	PR
432050	WELL	PA	07/10/2013	DA	123-36929	HOWARD 28C-33HZ	PA
432051	WELL	AL	05/24/2013	LO	123-36930	HOWARD 2C-33HZ	AL
432052	WELL	SI	12/01/2018	OW	123-36931	HOWARD 27C-33HZ	SI
432053	WELL	PR	04/10/2014	OW	123-36932	HOWARD 28C-33HZR	PR
432054	WELL	PR	04/13/2014	OW	123-36933	HOWARD 1C-28HZ	PR
432055	WELL	PR	04/14/2014	OW	123-36934	HOWARD 26N-28HZ	PR
434180	WELL	PR	04/23/2014	OW	123-38006	HOWARD 2N-33HZR	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: 4' barb wire

Corrective Action:

Date:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: LACT

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Type: Emission Control Device

4

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

6

Comment:

Corrective Action:

Date:

Type: Bradenhead

6

Comment:

Corrective Action:

Date:

Type: Pig Station

2

Comment:

Corrective Action:

Date:

Type: VRU

#

Comment:

Corrective Action:		Date:	
Type: Ancillary equipment	# 15		
Comment:	automation/electric boxes		
Corrective Action:		Date:	
Type: VRT	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspected Facilities

Facility ID: <u>242405</u>	Type: <u>WELL</u>	API Number: <u>123-10196</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432048</u>	Type: <u>WELL</u>	API Number: <u>123-36927</u>	Status: <u>PA</u>	Insp. Status: <u>PA</u>
Facility ID: <u>432049</u>	Type: <u>WELL</u>	API Number: <u>123-36928</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432050</u>	Type: <u>WELL</u>	API Number: <u>123-36929</u>	Status: <u>PA</u>	Insp. Status: <u>PA</u>
Facility ID: <u>432051</u>	Type: <u>WELL</u>	API Number: <u>123-36930</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>432052</u>	Type: <u>WELL</u>	API Number: <u>123-36931</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>432053</u>	Type: <u>WELL</u>	API Number: <u>123-36932</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432054</u>	Type: <u>WELL</u>	API Number: <u>123-36933</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432055</u>	Type: <u>WELL</u>	API Number: <u>123-36934</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>434180</u>	Type: <u>WELL</u>	API Number: <u>123-38006</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing WellComment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	11/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500241	Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980175