

Construction and Stormwater Inspection

November 4, 2019

Operator: EDGE ENERGY II LLC- #10671

Location ID: 456286

Inspection Document #: 697500773

Weld County, CO

NESE Section 26 T8N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 1. Photo taken from the entrance of location off HWY 85, facing South. Photo illustrates Operator has constructed and gravelled an access road.



Photo 2. Photo taken from the entrance of location off HWY 85, facing North. Photo illustrates Operator has installed a vehicle tracking device BMP.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 3. Photo taken along the access road, facing West toward HWY 85. It appears vehicle traffic is using this as an access point which should be prohibited.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 4. Photo taken from the western location, facing North. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.



Photo 5. Photo taken from the western location, facing South. See comments under Photo 4.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 6. Photo taken from the western perimeter of location, facing South. Photo illustrates a shallow ditch BMP along the western location. This ditch BMP would not be considered installed to a sufficient depth.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 7. Photo taken from the southwestern perimeter of location (north of the access road), facing South. Photo illustrates an ~3'x6' area of riprap at the end point of the ditch. This would not be considered a sediment trap.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 8. Photo taken from the southwestern perimeter of location (south of the access road), facing East. See comments under Photo 7.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 9. Photo taken from the southern perimeter of location, facing East. Photo illustrates sediment accumulation within the shallow ditch BMP. Also, Operator shall stabilized the unconsolidated fill material along the southern location as this is susceptible to wind and water erosion.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 10. Photo taken from the southeastern perimeter of location, facing North. See comments under Photo 7.



Photo 11. Photo taken from the northeastern perimeter of location, facing West. Photo illustrates the second topsoil stockpile which has been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 12. Photo taken from the northern topsoil stockpile, facing West. Photo illustrates equipment being stored on the topsoil stockpile which should be prohibited.