

Inspection Photos
Location Name: Ocoma 31-27
API ID: 123-17806



Photo #1 Wellhead & Sign

Inspection Photos
Location Name: Ocoma 31-27
API ID: 123-17806



Photo #2 Active leak at the casing collar. On 9/26/19

Photo #3 No Active leak at the casing collar. On 11/5/19

Inspection Photos
Location Name: Ocoma 31-27
API ID: 123-17806



**Photo #4 Active leak at the Meco regulator stainless fitting.
On 9/26/19**



**Photo #5 No Active leak at the Meco regulator stainless
fitting. On 11/5/19**